

LIGHT SOURCE REMOVING INSTRUCTION			Creation date (dd/mm/yyyy) :	20/05/2021
	Z Qui	ALITY	Last update date (dd/mm/yyyy) :	20/05/2021
1	rmation	Supplier's name or trade mark	INSPIRE	
2		Supplier's address	ADEO Services, 135 rue Sadi Carnot - CS0001, 59790 RONCHIN	
3	l info	Model Identifier - Luminaire Supplier reference	Zhejiang Tai-G Photoelectric Technology Co., Ltd.	
4	General	Light sources maker model	LED W13-349MH-C-N, LED W13-579MM-C-N, LED W13-909MM-C-N, LED W13-1209MM-C-N	

Instructions on how to remove lighting control parts and/or non-lighting parts, if any, or how to switch them off or minimise their power consumption during light source testing

	Explaination of the step	Pictures	Tools
Step 1	Open the end cap		Slotted screwdriver
Step 2	Cut the line between the light source and the drive	ASSESS TOT 200	scissors
Step 3	Take out the light strip		By hand
Step 4	The light source is attached to the cover	### ### ### ##########################	By hand
Step 5			
Step 6			