1 adeo		LIGHT SOURCE REMOVING INSTRUCTION	Creation date (dd/mm/yyyy) :	12/10/2022
	QUALITY		Last update date (dd/mm/yyyy) :	12/10/2022
1	tion	Supplier's name or trade mark	INSPIRE	
2	forma	Supplier's address	ADEO Services, 135 rue Sadi Carnot - CS0001, 59790 RONCHIN	
3	ner	Model Identifier - Luminaire Supplier reference	WE29211H91 - WH	
4		Light sources maker model	664#	

Instructions on how to remove lighting control parts and/or non-lighting parts, if any, or how to switch them off or minimise their power consumption during light source testing

	Explaination of the step	Pictures	Tools
Step 1	Loosen the screws with a screwdriver		screwdriver
Step 2	The screwdriver removes the plastic cover		screwdriver
Step 3	Remove plastic cover		hand
Step 4	Remove the terminal	752 Maria 3500V	scissors
Step 5	The LED module is fixed to the aluminum radiator	The contract of the contract o	hand
Step 6	Light source for SLR testing		hand
Step 7			
Step 8			
Step 9			