

PART LIST OF 750 DW-3

POS		DESCRIPTION	NUM	kit
1	JHCT087.01.001	Power cord	1	
2	JHCT014.01.092	float switch	1	
3	GB845 ST3.5×13-201	tapping screw	2	
4	JHCT001.02.005	handle cover	1	
5	JHCT003.03.027	back pump shell	1	
6	JHCT052.01.034	cable sheath	1	
6	JHCT052.01.036	cable sheath	1	
7	JHCT056.02.005	cable pressure buckle	1	
7	JHCT056.02.008	cable pressure buckle	1	
8	8uF-450V	capacitance 6 uf	1	
9	JHCT055.01.001	cable pressure block	1	
10	JHCT078.02.018	tapping screw	3	
11	JHCT026.02.004	rear cover	1	
11-1	JHCT052.02.003	cable sheath	1	
11-2	GB93 4	tapping screw	1	
11-3	JHCT086.01.010	yellow green line	1	
11-4	JHCT041.02.027	lug plate	1	
11-5	GB862.2 4	gasket	1	
11-6	GB818 M4×8	screw	1	
12	JHCT038.01.001	corrugated gasket	1	
13	GB/T276 6201-2Z	bearing	2	
14	JHCT023.01.002	rotor	1	
15	JHCT022.02.007	stator	1	
16	JHCT020.05.011	front lining ring	1	
17	JHCT038.02.023	gasket	1	
18	JHCT051.02.002	skeleton seal	3	
19	JHCT042.04.001	aluminum bushing	1	
20	JHCT051.01.052	o ring	1	
21	JHCT025.01.054	front cover	1	
22	JHCT051.01.010	o ring	1	
23	JHCT038.02.005-201	adusting washer	1	
24	JHCT009.03.036	impeller	1	
25	GB6182 M8-667	screw	1	
26	JHCT004.03.013	main pump shell	1	
26-1	GB308 6-201	steel ball	1	
26-2	JHCT038.04.004-201	minipad		
26-3	GB845 ST2.9×8.5-201	cross plate tapping screw	1	
27	JHCT078.02.005-TA-201	custom-made tapping screw	4	
28	JHCT051.01.015	o ring	1	Part no.:JHCT006.02.002 Description:Kit base(28-32)
29	JHCT006.02.002	pump base	1	
30	JHCT078.02.007-201	tapping screw	3	
31	JHCT007.01.002	base board	1	

32	GB845 ST4.2×13-F-201	tapping screw	3	
33	JHCT051.01.006	o ring	1	
34	JHCT028.03.001	elbow	1	
33	JHCT051.01.006	o ring	1	
35	JHCT027.03.001	Output Connector	1	
36	JHCT041.05.011	grounded shield	1	
37	JHCT041.01.001	nylon safe pressing line hat	2	
37	JHCT041.01.003	nylon safe pressing line hat	3	
38	JHCT032.03.012	rubber lined claw	1	
39	JHCT085.01.001	cable tie	1	

