



## M1Y-KZ-125迷你锯爆炸图清单 (230V-240V)

| 序号 | 名称及规格                                 | 数量 | 序号 | 名称及规格                                 | 数量 |
|----|---------------------------------------|----|----|---------------------------------------|----|
| 1  | Hesagan socket cap screw m6X10(left)  | 1  | 41 | pin                                   | 1  |
| 2  | flat washer 6 X12X1.6                 | 1  | 42 | reset compressed spring               | 1  |
| 3  | saw blade clamp                       | 1  | 43 | self-lock knob                        | 1  |
| 4  | saw blade Ø125                        | 1  | 44 | reset compressed spring               | 1  |
| 5  | saw blade clamp                       | 1  | 45 | trigger                               | 1  |
| 6  | saw balde clamp                       | 1  | 46 | seitch resetting spring               | 2  |
| 7  | gear box                              | 1  | 47 | right handle                          | 1  |
| 8  | saw blade cover                       | 1  | 48 | cross recessed tapping screw ST4.2X18 | 2  |
| 9  | cross head screw 4,X10                | 3  | 49 | cross recessed tapping screw ST4.2X16 | 6  |
| 10 | torsional spring                      | 1  | 50 | bearing 6000                          | 1  |
| 11 | protection cover                      | 1  | 51 | circlip for shaft 10                  | 1  |
| 12 | circlip for shaft 24                  | 1  | 52 | circlip for shaft 10                  | 1  |
| 13 | pointer to the lock shaft             | 1  | 53 | gear of the output shaft              | 1  |
| 14 | depth needle seat                     | 1  | 54 | output shaft                          | 1  |
| 15 | limit circle                          | 1  | 55 | flat key 3X3X10                       | 1  |
| 16 | saw blade cover                       | 1  | 56 | needle bearing 8X12X8                 | 1  |
| 17 | pointer                               | 1  | 57 | out gear box cover                    | 1  |
| 18 | cross combination screw M4,X20        | 1  | 58 | cross combination screw M4,X10        | 3  |
| 19 | eccentric button                      | 1  | 59 | cross combination screw M4,X10        | 1  |
| 20 | cylindrical pin 3X15                  | 1  | 60 | head shell cover                      | 1  |
| 21 | cross combination screw M4,X10        | 1  | 61 | self-lock pin                         | 1  |
| 22 | Hesagan socket cap screw m6X50        | 1  | 62 | self-lock compressed spring           | 1  |
| 23 | accompany cover                       | 1  | 63 | E circlip 5                           | 1  |
| 24 | Hesagan socket cap screw m6X35        | 1  | 64 | small gear                            | 1  |
| 25 | dust collection conduit               | 1  | 65 | bearing 6000                          | 1  |
| 26 | cross combination screw M4,X10        | 2  | 66 | circlip for shaft 26                  | 1  |
| 27 | supporting base                       | 1  | 67 | gear shaft                            | 1  |
| 28 | bottom plate                          | 1  | 68 | needle bearing 8X12X8                 | 1  |
| 29 | stepped screw                         | 1  | 69 | gear box cover                        | 1  |
| 30 | cross head screw 4X6                  | 5  | 70 | cross combination screw M4,X10        | 4  |
| 31 | ruler knob                            | 1  | 71 | bearing 6000                          | 1  |
| 32 | guide ruler                           | 1  | 72 | rotor                                 | 1  |
| 33 | left handle                           | 1  | 73 | bearing 627                           | 1  |
| 34 | cable                                 | 1  | 74 | bearing sleeve                        | 1  |
| 35 | cable clamp                           | 1  | 75 | Hesagan socket cap screw m4,X12       | 2  |
| 36 | cross recessed tapping screw ST4.2X13 | 2  | 76 | cross recessed tapping screw ST2.9X6  | 1  |
| 37 | cable sheath                          | 1  | 77 | battery cell                          | 1  |
| 38 | capacitor                             | 1  | 78 | button cell                           | 1  |
| 39 | switch                                | 1  | 79 | laser switch                          | 1  |
| 40 | lever                                 | 1  | 80 | laser cover                           | 1  |

## M1Y-KZ-125迷你锯爆炸图清单 (230V-240V)

[illegible]

编制:

校对:

核审

批准:

编制:

校对:

审核

批准: