

	Document missing
---	------------------

Product identification			
------------------------	--	--	--

Adeo Ref	Product EAN	Supplier ref	
809008	3276007540482	LR1- 1B	
808998	3276007540512	CR2016- 2B	
809035	3276007540529	CR2025- 2B	
809025	3276007540536	CR2032- 2B	
809012	3276007540550	CR2450- 2B	
809031	3276007540543	CR2430- 2B	
808994	3276007540239	CR2025- 4B	
809002	3276007540208	CR2032- 4B	
809032	3276007540352	CR2025-6B	
809038	3276007540321	CR2032-6B	
808999	3276007540505	LR44- 2B	
809039	3276007540246	LR54- 1B	
809010	3276007540314	CR123A 1B	
809014	3276007540284	CR2 1B	
809018	3276007540499	23A- 1B	

Template version history			
--------------------------	--	--	--

Version	Status	Date Status	Comments
V.0	Under construction	20/08/2018	Template construction

Object

In case of supplier cannot provide related documents on time, or the document is not necessary to provide as confirmed by ADEO QM, supplier could use the missing documents template to replace required document.

NINGBO BATTERY & ELECTRICAL APPLIANCE I/E CO., LTD

128 Xingguang road,Hi-Tech Part,Ningbo,China

Type of document missing	Cause
Declaration Technical Regulation Ukraine	this report is not applicable for this product
SA Letter of Authorization (LOA)	this report is not applicable for this product
Instructions manual(s)	this report is not applicable for this product